

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	16916	air WITH reduc\$4 WITH oxygen	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:04
L2	545111	foam\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:04
L3	545111	foam\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:04
L4	1051	1 and 3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:07
L5	932690	drilling or workover or cementing or spacer\$1 or gravel\$1pack\$3 or acidizing or fracturing or completing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:10
L6	1025082	drilling or workover or cementing or spacer\$1 or gravel\$1pack\$3 or acidizing or fracturing or completing or stimulating	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:11
L7	206	4 and 6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:15
L8	842	air SAME (oxygen NEAR5 scaveng\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:31

L9	2	7 and 8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:13
L10	137	3 and 8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/22 09:32